ercot\$

Gulf Coast Power Association (GCPA) Spring 2016 Conference

Session III Cost Allocation Issues in Transmission

Session Moderator:

Chad V. Seely, ERCOT

General Counsel

Panelists:

Amanda Frazier, Energy Future Holdings
Director of Regulatory Policy

Jaren Taylor, Vinson & Elkins
Attorney

Charles Yarbrough II, Atmos Energy
Vice President, Rates and Regulatory Affairs,

April 12, 2016

A Battle Among Classic Titans

Resource Entities vs. Transmission Utilities vs. Gas Utilities













SSR Incident – Mohave Generator (1970)






Fig. 7. Synchronization Frequency Analysis



SSR Criteria – The Current Proposal

Scope	Frequency Scan Criteria	Frequency Range
IGE/SSCI	Positive resistance at reactance crossover frequency (Generator + System)	5 ~ 55 Hz
TI	Positive Total Damping (Electrical De + Mechanical Dm) Dm at +/- 1 Hz of the modal frequency is utilized to compare to De.	5 ~ 55 Hz
TA	Less than 5% reactance dip within +/- 3Hz of the 60 Hz complement of a modal frequency. *	5 ~ 55 Hz


Option	Generation	Mitigation (# of outages)	Protection (# of outages)	Outage Coordination / Monitoring
NPRR562	All Resources			N=5,6, ERCOT/TSP
Ontion 1	New Generation	N<=4, GO	na	N=5,6, ERCOT/TSP
	Existing Generation	N<=4, TSP	na	N=5,6, ERCOT/TSP
Option2	New Generation	N<=4, GO	na	N=5,6, ERCOT/TSP
	Existing Generation (after NPRR562)	N<=3, GO	N=4, GO	N=5,6, ERCOT/TSP
	Existing Generation	N<=4, TSP	na	N=5,6, ERCOT/TSP



Induced Voltage – Possible Accelerated Corrosion







Induced Current – NACE International Standard

From NACE SP0117-2014 Foreword:

• "Many are now concerned with AC corrosion on buried pipelines adjacent to or near overhead electric transmission towers. This subject is not quite fully understood, nor is there an industry consensus on this subject. There are reported incidents of AC corrosion on buried pipelines under specific conditions, and there are also many case histories of pipelines operating under the influence of induced AC for many years without any reports of AC corrosion. The members of NACE Task Group (TG) 025 agreed that any criteria for AC corrosion control should not be included in this standard."





